SERVICE TOOLS

Accessories

PHOTO TACHOMETER

bient light areas.

WITH PTFE®

controlled crystal display.

· Infrared light source, micro-processor

Machine speed: It is critical for proper ma-

chining operations. Speeds too fast or too

slow can shorten tool life and cause expen-

sive, unnecessary machine downtime. This

digital photo tach can take readings from

revolving shafts on drill presses, grinders,

lathes and other machines. It can also be

used to check engine operation on in-plant

vehicles like forklifts. The 3344 is accurate

to within ± 1 rpm. The $\frac{13}{32}$ " high liquid crys-

tal display is easily visible even in high am-

HTS50 HEAVY-DUTY PIPE SEALANT

· Seals new or damaged threads; resists

· Replaces conventional tape methods; forms

a clog-free seal. Effective at 10,000 psi.

When "plumbing" a hydraulic system, there's

tear or shred, possibly plugging filters, valves or gauges. This compound combines the lubri-

Even the seemingly simple job of removing

7312 all metal "O" ring seal pick does the

without the aid of the proper tool. The

now a better answer than tapes which can

water, chemicals and oils.

"O" RING SEAL PICKS

· Strong magnetic base is included.



3344A

Range: 200 to 9999 rpm. Accuracy: ± .25%. ± 1 rpm. Update time: 3/4 second. Power switch: Membrane switch (automatic shut-off after one minute of no signal input). Power source: 9 volt alkaline battery. Light source: Infrared with 15-foot plug-in cable. Light holder assembly: 30 lb. rated magnet; dia. x 1/4" high (4" high overall with post). **Size:** 3³/₈" w, 6" h x 1¹/₂" d. **C case:** 13¹/₂" w, 10" h x 4" d.

(PTFE is a registered trademark of duPont Co.)


HTS50







No. HTS50 - Sealant, 50 ml. tube. Wt., 0.4 lb.



No. 45329 - Replacement photo probe assembly. Wt., 0.4 lb.

No. 3344A - Digital Photo Tachometer. With memory,

base, 108" of reflective tape

and plastic case. Wt., 4.5 lbs.

No. 39811 - Replacement mag-

netic base assembly. Wt. 0.3 lb.

No. 204666 - Replacement retro-reflective indicator tape, 108" long x $\frac{1}{2}$ " wide. Wt., 0.1 lb. **SPECIFICATIONS**

Readout: Liquid crystal display: 4 (13/32" high) digits, low battery indicator, memory mode indicator, high and low RPM memory mode indicator.

cating qualities of PTFE with a fast curing anaerobic sealant. Seals all metal fittings, plugs and threaded joints quickly and easily. Cures to form a permanent seal which is inert to hydrocarbons, most acids, chemicals, solvents and steam. Allows adjustment up to 16 hours after assembly; cannot loosen under vibration. Prevents galling of mating parts upon disassembly. Withstands temperatures from 65° F to +375° F.

job with ease. Two special picks in set No. 7103 get right to the trouble areas. No. 7312 - "O" ring seal pick. Wt., 0.1 lb. and installing "O" ring seals can be difficult No. 7103 – Set of two "O" ring seal picks. Wt., 0.1 lb.

TOOLS

UNIVERSAL OUTSIDE THREAD CHASER No. 7402 - Thread chaser, complete

Restore damaged threads on shafts, housings, cages, etc., for re-assembly of matching parts. Eliminates need for thread-cutting equipment. Will not harm threads. V-pads and dies can be replaced. Cap. 11/4" to 5" O.D.

(with 6 dies: threads per inch - 4, 5, 6, 7, 71/2, 8, 9, 10, 11, 111/2, 12, 14, 16, 18, 20 and 24). Wt., 4.5 lbs.

No. 202817 - Metric die set (3 dies: mm per thread: 1, 1.25, 1.5, 1.75, 2, 2.5, 3, 3.5, and 4). Wt., 0.2 lb.



MAGNETIC PICK-UP TOOL

Has permanent magnetic head for retrieving parts from otherwise inaccessible places. No. 7395 - Pick-up tool with pocket clip. 6" lg. Wt., 0.1 lb.



POWER TEAM

188